


Australia only

Make sure the thermostat is adjusted to 60°C, as shown below



6720647035-01.2V

